

# VISIR COLOURLESS

## Unpigmented, solvent-borne wood primer



G020210 08.2003

Visir Colourless is an unpigmented oil primer for planed exterior softwood (spruce and pine). The product is based on alkyd oil, combined with zinc octoate, and is moderately thixotropic. Visir Colourless penetrates well into the substrate, and may be used throughout the year. Visir Colourless is well suited as an oil primer under oil stains in light colours, if one wishes to keep as much as possible of the wood structure.

### PHYSICAL DATA:

Type.....	Primer, based on alkyd oil and zink octoate
Colour.....	Clear
Viscosity.....	Approx. 40 sec. (EN 535-3)
Specific gravity.....	0,84
Solids by volume %.....	Approx. 19
Flash point, degrees centigrade.....	63

### RECOMMENDATION FOR USE:

Recommended spreading rate, sawn wood .....	5 - 12 m <sup>2</sup> /litre
Recommended spreading rate, planed wood .....	12 - 18 m <sup>2</sup> /litre
Application methods.....	Brush designed for stains
<b>Drying times, (guiding data at 23 deg. C, 50% R.H.):</b>	
Dust dry.....	8 hours
Interval between coats.....	24 hours
Dry to use.....	Drying time deviates, depending on temperature, wind conditions and film thickness hours
Thinner/cleaning agent.....	White Spirit

### SAFETY DATA:

A Material Safety Data Sheet has been issued for this product

### MISCELLANEOUS:

Size of containers.....	1, 3 and 10 litres
-------------------------	--------------------

### DIRECTIONS FOR USE:

#### PRETREATMENT:

The surface must be clean and dry before treatment. Round off sharp edges. Loose wood fibres must be removed by wire brush or sanding.

**METHODS OF USE:**

New wood: To be treated before or immediately after mounting with one coat Visir Colourless. Wood that has been exposed more than 3 weeks must be inspected, and if necessary, washed and sanded. Visir Colourless may also be used as a primer under translucent products, and even as a primer on various hardwoods, prior to treatment with Benar.

Wood previously treated with translucent stain, opaque stain or paint: Contaminated/fungus infected surfaces must be washed with a suitable detergent. Remember to rinse well with fresh water. Loose paint/loose wood fibres must be removed. Bare wood to be given 1 coat Visir Colourless. On particularly absorbent surfaces 2 coats (wet-on-wet) may be necessary. Observe that Visir Colourless should not form a film on the surface, excess should be wiped off with a rug.

**REMARKS:**

Surfaces primed with Visir Colourless should be re-coated as soon as possible, and no later than 3 months from priming. Visir Colourless is ready for use, and should not be diluted. Remember to treat all end grain well, 3 - 4 coats, wet-on wet.

---

The above information is given to the best of our knowledge based on laboratory tests and practical experience. However, as the product is often used under conditions beyond our control, we cannot guarantee anything but the quality of the product itself. We reserve the right to change the given data without notice.

Paint should be looked upon as a semi-manufacture. The result is dependent on construction, the condition of the substrate, pre-treatment, temperature, relative air humidity, application etc.

---